



















SCHNITT A-A























SCHNITT B-B











| | | |
|---|---------------|---|
| 4 | 120-M20 Teil4 | 1 |
| 5 | 120-M20 Teil5 | 1 |
| 6 | 120-M20 Teil6 | 1 |

