






















SCHNITT A-A
























SCHNITT D-D












SCHNITT F-F





4	130-M12 Teil4	1
5	130-M12 Teil5	1
6	DIN 936 M12	2
7	130-M12 Teil6	2

