


















SCHNITT A-A












D





SCHNITT D-D





D








1,50















1 X 45° SCHNITT E-E





SCHNITT F-F





4	130-M20 Teil4	1
5	130-M20 Teil5	1
6	DIN 936 M20	2
7	130-M20 Teil6	2

