















DIN 914
M5x4


















M8





2x ϕ 6,50



















SCHNITT E-E







4	51264-240 Teil6	1
5	DIN 7380 M6x10	1
6	DIN7991 M6x12	1
7	51264-240 Teil2	1
8	51264-240 Teil3	1
9	DIN 913 M5x3	1
10	DIN 914 M5x4	1

